

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY SUPERFUND SITE STRATEGY RECOMMENDATION - REGION 06



ddress: 348 Malvern Ave	
City/County or Parish/State/Zip Code: Hot Springs/Garland/AR	
eport Type, Date, and Author: PA, March 3	1 1993 Fluor Daniel
ECOMMENDATION	
(x) 1. Site Evaluation Accomplished (SEA)	() 2. Further Investigation Nevded Under Superfund
	() PA () HRS Priority: () High
	() SI () RA () Low () ESI () RI/FS
	() Other;
() 3. Action Deferred to:	To be performed by:
() RCRA () NRC	
OTIFY AUTHORITY:	
Till Admonth.	
) Removal () RCRA	() TSCA () CAA () SMCGA
. Adm.dial () State	() Nippre
) CERCLA Enforcement () Federal Facility SEND REPORT COPIES TO: (XISE-F	() UIC () SPCC () Other:
17	(X) 6W-SP (X) ATSDR (X) State Agency () Other
	(PA) for this site, completed by the ARCS contractor Fluor Daniel was reviewed. This sit at 1800s, for an unknown period of time. The coal gastication processes reportedly wastes. The risk is executed to the coal gastication processes reportedly wastes.
roduced large amounts of city, sludge-like company. There is a three level structure of sconnaissance in 1993, conducted as part slease of hazardous substances to the soil, source of drinking water in this area. There	n-site. Site visits during the Field Verification Study in 1991 and during the site
roduced large amounts of city, sludge-like company. There is a three level structure of sconnaissance in 1993, conducted as part slease of hazardous substances to the soil, source of drinking water in this area. There	n-site. Site visits during the Field Verification Study in 1991 and during the site of the PA, did not find any evidence of surficial contamination. There is no evidence that ground water, surface water or air has occurred at this site. Ground water is not used a late of the PA.
roduced large amounts of city, studge-like company. There is a three level structure o econnaissance in 1993, conducted as part elease of hazardous substances to the soil, source of drinking water in this area. There ased on the results of the PA, a decision of the part of the part of th	n-site. Site visits during the Field Verification Study in 1991 and during the site of the PA, did not find any evidence of surficial contamination. There is no evidence that ground water, surface water or air has occurred at this site. Ground water is not used a are no residences, schools, or daycare facilities located within 200 feet of the site. I Site Evaluation Accomplished is recommended for this site.
roduced large amounts of city, studge-like company. There is a three level structure o econnaissance in 1993, conducted as part slease of hazardous surbatances to the soil, source of drinking water in this area. There ased on the results of the PA, a decision of IPPROVALS:	n-site. Site visits during the Field Verification Study in 1991 and during the site of the PA, did not find any evidence of surficial contamination. There is no evidence that ground water, surface water or air has occurred at this site. Ground water is not used a are no residences, schools, or daycare facilities located within 200 feet of the site. I Site Evaluation Accomplished is recommended for this site. Signature: Date Aug/25/93
reduced large amounts of city, sludge-like tompany. There is a three level structure o company. There is a three level structure o connaissance in 1993, conducted as part of elease of hazardous substances to the soil, source of drinking water in this area. There ased on the results of the PA, a decision of the PROVALS:	n-site. Site visits during the Field Verification Study in 1991 and during the site of the PA, did not find any evidence of surficial contamination. There is no evidence that ground water, surface water or air has occurred at this site. Ground water is not used a are no residences, schools, or daycare facilities located within 200 feet of the site. I Site Evaluation Accomplished is recommended for this site. Signature: Date: Aug/25/93
roduced large amounts of city, studge-like company. There is a three level structure o beconnaissance in 1993, conducted as part slease of hazardous surbatances to the soil, source of drinking water in this area. There ased on the results of the PA, a decision of IPPROVALS: eport Reviewed by: John L. Jones isposition Recommended by: Eddie A. Sierre location Chief)	n-site. Site visits during the Field Verification Study in 1991 and during the site of the PA, did not find any evidence of surficial contamination. There is no evidence that ground water, surface water or air has occurred at this site. Ground water is not used a are no residences, schools, or daycare facilities located within 200 feet of the site. I Site Evaluation Accomplished is recommended for this site. Signature: Date Aug/25/93
reduced large amounts of city, studge-like company. There is a three level structure o company. There is a three level structure o connaissance in 1993, conducted as part stocase of hazardous substances to the soil, source of drinking water in this area. There ased on the results of the PA, a decision of the PROVALS; eport Reviewed by: John L. Jones is position Recommended by Eddie A. Sierra	n-site. Site visits during the Field Verification Study in 1991 and during the site of the PA, did not find any evidence of surficial contamination. There is no evidence that ground water, surface water or air has occurred at this site. Ground water is not used a are no residences, schools, or daycare facilities located within 200 feet of the site. If Site Evaluation Accomplished is recommended for this site. Signature: Date: Aug/25/93